



Valve Spindle – Valve Stem

Food Processing –Vegetable Steam Peeling

General Information

Customer: Odenberg, Belgium
Product: Valve Stems
Application: Vegetable Steam Processing
Install Date: 2006

Problem

The vegetable plant experienced heavy corrosion. It has been observed that the 36 mm diameter spindle in AISI 316L has completely eroded in a time frame of 4 months.

Solution


A **Tantaline JobShop** solution was applied in the spring 2006.

Result

The Tantaline valve spindles are still in use and no failures have been reported to date.



Odenberg part no. P0101192



www.tantaline.com